

## Bug List

Issuetracker #	Bug#	Customer Ref.#	Name	Release	Priority
7856	165	FH_QL-732	Test screen does not check and flag test method quality requirements	3.3.900 RC!	Medium (Priority 3)
7634	174	BUG177	External Document set to complete	3.3.900 RC!	Medium (Priority 3)
7595	178	FH_QL-648	Benkelman Beam Calibration	3.3.900 RC!	Medium (Priority 3)
7451	191	FH_QL-555	XML Test Report Accreditation Logo	3.3.900 RC!	Medium (Priority 3)
8105	215	BUG189	ASTM D 422 Hydrometer-Sieve Analysis	3.3.900 RC!	High (Priority 2)
8100	217	BUG188	Items missing from ASTM D 5084 test report	3.3.900 RC!	High (Priority 2)
8053	218	BUG184	AASHTO Proctors	3.3.900 RC!	High (Priority 2)
	261	BOR_97	CBR Q113A Method Issues - Defer into LAB v3.3	3.3.900 RC!	High (Priority 2)
	272	BUG198	Marshall Stability - MnDOT 1805	3.3.900 RC!	Low (Priority 4)
	273	QL-1173	User Test Reports	3.3.900 RC!	High (Priority 2)
	274	BUG199	200 Wash ASTM C 117	3.3.900 RC!	Low (Priority 4)
	275	BUG200	200 Wash AASHTO T 11	3.3.900 RC!	Medium (Priority 3)
	277	BUG197	Visual-Manual Identification (ASTM D 2488)	3.3.900 RC!	Medium (Priority 3)
	311	PSI 652	Archived test reports not in consistent order in QESTLab tree	3.3.900 RC!	Urgent (Priority 1)
	414	BOR_139	Multiple emails appearing when sending test report via email	3.3.900 RC!	High (Priority 2)
	464	n/a	Q208B Test screen error message	3.3.900 RC!	High (Priority 2)
	465	1308836	Sampling Procedure and Sampling Method naming is incorrect	3.3.900 RC!	High (Priority 2)
	495	BOR_129	Flakiness mass of fraction showing incorrect data	3.3.900 RC!	High (Priority 2)
	501	BUG214	Asphalt Core Report Rounding	3.3.900 RC!	Medium (Priority 3)
7685	530	QL-686	XML Test Report Issues	3.3.900 RC!	High (Priority 2)
	684	1300159	Mass of Aggregate is not to one decimal place (AS 1141.22)	3.3.900 RC!	High (Priority 2)
	704	1379879	Deg factor AS1141.25.2 not showing on Test Report	3.3.900 RC!	High (Priority 2)
	766	AQUA3	NCR screen shows only first person in User list in dropdowns	3.3.900 RC!	High (Priority 2)
	894	747	Measured By / Tested By Copy Function Does Not Copy Down	3.3.900 RC!	High (Priority 2)
	898	HoI_314	HoI_314 - Q113A Multipoint CBR - values on individual test screen appear incorrect	3.3.900 RC!	Urgent (Priority 1)
	936	1380217	Order Number not being inserted at docket Import-insert level	3.3.900 RC!	High (Priority 2)
	982	QL-1972	Brookfield Viscosity	3.3.900 RC!	High (Priority 2)
	991	QL-1977	Sand Circle Test	3.3.900 RC!	High (Priority 2)
	993	BUG 222	Concrete Cure reporting	3.3.900 RC!	High (Priority 2)
	995	BUG 224	Concrete bulk measuring, testing, and checking	3.3.900 RC!	High (Priority 2)
	1060	QL-2022	Doc 10274 Modifications	3.3.900 RC!	High (Priority 2)
	1072	N/A	RE: Support request for -Compactability Index not available	3.3.900 RC!	Medium (Priority 3)
	1080	QL-2094	Document 10120 - Method Update	3.3.900 RC!	High (Priority 2)
	1156	BUG187	ASTM D 2166 Unconfined Compressive Strength	3.3.900 RC!	High (Priority 2)
	1158	n/a	Q142A Missing Reporting Items	3.3.900 RC!	Medium (Priority 3)

## Bug List

Issuetracker #	Bug#	Customer Ref.#	Name	Release	Priority
	1166	795	Parent Documents Not Ordered by QESTID	3.3.900 RC!	Low (Priority 4)
	1168	Cof11.072	Project code not showing after adding new Project to list.	3.3.900 RC!	Medium (Priority 3)
	1173	n/a	User documents cannot contain comma	3.3.900 RC!	Low (Priority 4)
	1174	Cof11.042	Slow printable worksheets - batch print jobs together	3.3.900 RC!	High (Priority 2)
	1175	n/a	Bulk entry - some fields fail to cache, do not appear on external documents	3.3.900 RC!	Medium (Priority 3)
	1187	BUG 229	Concrete plant on report	3.3.900 RC!	Medium (Priority 3)
	1189	BUG 226	MnDOT 1305 Standard Proctor Correction	3.3.900 RC!	Medium (Priority 3)
	1193	QL-2177	ND Data Entry View and report	3.3.900 RC!	High (Priority 2)
	1195	n/a	Cleanup and fixing of external document options	3.3.900 RC!	Medium (Priority 3)
	1200	BUG 231	Selecting Other Masonry Type	3.3.900 RC!	High (Priority 2)
	1201	n/a	Converted Wet Density is Crashing	3.3.900 RC!	Urgent (Priority 1)
	1206	n/a	Specification notation: "-" vs "to"	3.3.900 RC!	Medium (Priority 3)
	1207	806	Atterberg Limits: Typo	3.3.900 RC!	High (Priority 2)
	1209	807	Reduced Icon Not Displayed - Specifications	3.3.900 RC!	Low (Priority 4)
	1212	n/a	AS2891.9.2 - FieldTest Method - Lot ConfirmityMissing	3.3.900 RC!	Urgent (Priority 1)
	1215	n/a	List Entries Can't Be Deleted	3.3.900 RC!	Urgent (Priority 1)
	1216	Cof11.026_UAT	PSD Not Clearing Moisture Content	3.3.900 RC!	High (Priority 2)
	1217	Cof11.031_5	Random lot generator - edge boundaries not correct	3.3.900 RC!	High (Priority 2)
	1218	808	Triaxial Compression for Disturbed Soils and Base Materials [Tex-117-E]	3.3.900 RC!	High (Priority 2)
	1219	n/a	Marhsall Stability LBF	3.3.900 RC!	High (Priority 2)
	1220	809	Measuring Thickness of Pavement Layer [Tex-140-E]	3.3.900 RC!	High (Priority 2)
	1221	812	Tex-103-E UAT	3.3.900 RC!	Medium (Priority 3)
	1223	811	Proctor Tex-113-E and Tex-114-E	3.3.900 RC!	Medium (Priority 3)
	1224	810	Sieve Analysis for Fine and Coarse Aggregate [Tex-401-2] and Tex-200-F, Tex-229-F, Tex-110-E, Tex-111-E, Tex-101-E	3.3.900 RC!	High (Priority 2)
	1225	EXPANSION	Expansion Index Report not reporting method	3.3.900 RC!	High (Priority 2)
	1226	816	Help Menu - ? not i	3.3.900 RC!	Medium (Priority 3)
	1228	PEOPLE	Clicking on the Save icon crashes People and Roles	3.3.900 RC!	High (Priority 2)
	1231	815	Work Order Template Lab Context	3.3.900 RC!	High (Priority 2)
	1236		External document metadata inefficiencies	3.3.900 RC!	Medium (Priority 3)
	1248	825	Asphalt Content [Tex-236-F]	3.3.900 RC!	High (Priority 2)
	1251	QL-2192	ASTM D 4867 Moisture Susceptability Test	3.3.900 RC!	Medium (Priority 3)
	1254	n/a	Options.OptionName value not populated when options are set/created	3.3.900 RC!	High (Priority 2)
	1257	826	Lab Tech Locked on WO load	3.3.900 RC!	Medium (Priority 3)
	1264		Ticking "Group" checkbox on Work Template Screen causes a fatal crash	3.3.900 RC!	High (Priority 2)
	1265	QL-1956	Uniformity & Curvature Coefficients	3.3.900 RC!	High (Priority 2)

## Bug List

Issuetracker #	Bug#	Customer Ref.#	Name	Release	Priority
	1267	BUG176	Proctor Test Report	3.3.900 RC!	Medium (Priority 3)
	1268		'Jump to Role' button not enabling on single-lab system	3.3.900 RC!	High (Priority 2)
	1269	QL-2278	DOC 117113 Height, Stab, Flow etc	3.3.900 RC!	High (Priority 2)